

NELAC NY 11769 NRPP 101193 AL NRSB ARL0017 EPA Method #402-R-92-004 Liquid Scintillation NRPP Device Code 8088 NRSB Device Code 12193

Laboratory Report for:

**Property Tested:** 





| Log Number | <b>Device Number</b> | Area Tested | Result (pCi/L) |
|------------|----------------------|-------------|----------------|
| 2055154    | 3283661              | Basement    | 3.4            |
| 2055155    | 3283662              | Basement    | 3.9            |

Radon test results are below the EPA action level of 4 pCi/L. No further action is required at this time. The EPA suggests that you may want to test again in the future to ensure that radon levels remain below the action level. If the property tested uses water from a private well, you may wish to consider testing for radon in water.

**Comment:** Clayton Home Inspection, Inc. was e-mailed a copy of this report. A copy of this report was emailed to yang@purdue.edu.

Distributed by: Clayton Home Inspection, Inc.

 Test Began:
 02/28/2017
 12:20 pm
 Date Received:
 03/06/2017
 Date Analyzed:
 03/07/2017

 Test Ended:
 03/02/2017
 5:10 pm
 Date Logged:
 03/06/2017
 Date Reported:
 03/07/2017

Test Exposure Duration: 52.8 Hours

Carolyn D. Koke, President, AccuStar Labs

## Disclaimer:

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.